

BRITISH WIRING INC.

P.O. BOX 185

617 WALNUT STREET

BALLY, PA 19503

Toll Free: 866-461-9050

Fax: 610-845-3518

[e-mail: britishwiring@ameritech.net](mailto:britishwiring@ameritech.net)[web page: www.britishwiring.com](http://www.britishwiring.com)

Note: The plastic plug housings for the ODD number (only) "Spade" and "Tab" multi-wire connectors are no longer available. The even number (of wire) plastic connector housings are still available at this time. Unless otherwise specified, for the plugs that are not available, the metal terminals will be put on the wire ends in the hope that the original plastic plug housings can be reused. If not please call for options.

Wire	Wrap	Description
P	P	PVC wire and PVC tape outer wrap.

Headlamp Pigtails for the Models in this Listing - need 2 per car

Part #	Wire	Wrap	Pcs	Wrap	Blue/White (UW) wire	Blue/Red (UR) wire	Black (B) ground wire
141	P	P	1	PVC	PVC	PVC	PVC

JENSEN HEALEY

Part #	Wire	Wrap	Pcs	Year	Model, Series, Chassis # and Identifying Features	
90586	P	P	1		Main Harness, upto # 13349	LHD
92991	P	P	1		Main Harness, # 13350 - on	
97764	P	P	1		Main harness, # ????????	LHD, US spec
90843	P	P	1		Panel Harness	
97049	P	P	1		"Engine" harness which does the alternator and starter	# 13350 - on
99211	P	P	1		"Engine" harness, later style with two 5 pin connectors	LHD, US spec

JENSEN INTERCEPTOR, Mk 2, 1969-71, all cars up to # 5865**LHD Vin# prefix =125,**

Part #	Wire	Wrap	Pcs	Year	Model, Series, Chassis # and Identifying Features	
6489	P	P	1		Main harness	CT 6489
6468	P	P	1		Body harness	Need Pattern
3916	P	P	1	Choose	Facia panel harness, early Mk 2	CT 3916
6484	P	P	1	or	Facia panel harness, later Mk 2	CT 6484
4468	P	P	1	Choose	Switch panel harness - early Mk2	CT4468
6398	P	P	1	or	Switch panel harness - later Mk2	CT 6398
3596	P	P	1		Electric Windows and gearbox harness	CT 3596
3920	P	P	1		Interior lights	CT 3920
6401	P	P	1		Gearbox harness	CT 6401
6235	P	P	1	1970-on	Clock harness	CT 5235
6485	P	P	1		Right hand side door harness	CT 6485
6486	P	P	1		Left hand side door harness	CT 6486
4261	P	P	1		Front cover plate harness	Need Pattern
4260	P	P	1		Rear cover plate harness	Need Pattern

JENSEN INTERCEPTOR, Mk 3, 1971-73, all cars from 5866 to 8967**LHD Vin# prefix =133 for G (1971), H (1972) & most J (1973) series****LHD Vin# prefix=140 for later J (1973) series**

Part #	Wire	Wrap	Pcs	Year	Model, Series, Chassis # and Identifying Features	
7154	P	P	1		Forward harness	CT 7154
7153	P	P	1		Body Harness	CT 7153
7156	P	P	1		Facia panel harness	CT 7156
6398	P	P	1		Switch panel harness	CT 6398
3920	P	P	1		Interior lights	CT 3920

JENSEN INTERCEPTOR, Mk 3, 1971-73, 5866 to 8967 - continued

Part #	Wire	Wrap	Pcs	Year	Model, Series, Chassis # and Identifying Features	
6401	P	P	1		Gearbox harness	CT 6401
6485	P	P	1		Right hand side door harness	CT 6485
7152	P	P	1		Left hand side door harness	CT 7152
7460	P	P	1	-73-	Ignition switch relay harness	CT 7460
7549	P	P	1	-73-	Panel light resistor harness	CT 7549
4261	P	P	1		Front cover plate harness	Need Pattern
4260	P	P	1		Rear cover plate harness	Need Pattern

JENSEN INTERCEPTOR, Mk 3, late 73-on, all cars from 8968 to 2310/1288

Starting in 1974 VIN numbering changed to the system below:

LHD Vin# prefix =2210 for Federal saloon, 2211 for California saloon

LHD Vin# prefix =2310 for Federal convertible, 2311 for California

LHD Vin# prefix =2710 for Federal coupe, 2711 for California

Part #	Wire	Wrap	Pcs	Year	Model, Series, Chassis # and Identifying Features	
7151	P	P	1		Switch interchange harness	CT 7151
7564	P	P	1		Park switch extension harness	CT 7564
7154	P	P	1		Forward harness	CT 7154
7153	P	P	1		Body Harness	CT 7153
7156	P	P	1		Facia panel harness	CT 7156
6398	P	P	1		Switch panel harness	CT 6398
3920	P	P	1		Interior lights	CT 3920
6401	P	P	1		Gearbox harness	CT 6401
6485	P	P	1		Right hand side door harness	CT 6485
7152	P	P	1		Left hand side door harness	CT 7152
7460	P	P	1	-73-	Ignition switch relay harness	CT 7460
7549	P	P	1	-73-	Panel light resistor harness	CT 7549
4261	P	P	1		Front cover plate harness	Need Pattern
4260	P	P	1		Rear cover plate harness	Need Pattern
51009	P	P	1		Optional roof operation harness - for convertible only	

JENSEN INTERCEPTOR, Mk 3, up to 76 (end), all cars from 2310/1289 - on

Starting in 1974 VIN numbering changed to the system below:

LHD Vin# prefix =2210 for Federal saloon, 2211 for California saloon

LHD Vin# prefix =2310 for Federal convertible, 2311 for California

LHD Vin# prefix =2710 for Federal coupe, 2711 for California

Part #	Wire	Wrap	Pcs	Year	Model, Series, Chassis # and Identifying Features	
7673	P	P	1		Forward harness	CT 7673
7672	P	P	1		Body harness	CT 7672
7671	P	P	1		Facia panel, has switch panel & gearbox wiring built in	CT 7671
7807	P	P	1		Interior lights	CT 7807
7667	P	P	1		Right hand side door harness	Need Pattern
7668	P	P	1		Left hand side door harness	CT7668
7460	P	P	1	-73-	Ignition switch relay harness	CT 7460
7549	P	P	1	-73-	Panel light resistor harness	CT 7549
7808	P	P	1		Oil pressure switch extension lead with warning light.	CT 7808
7810	P	P	1		Heated rear window earth wire.	CT 7810
7811	P	P	1		Heated rear window feed wire.	CT 7811
7812	P	P	1		Right hand flasher repeater lead	CT 7812
7844	P	P	1		Aerial switch extension lead	CT7844
7674	P	P	1		Balance control and speaker harness	CT7674
4261	P	P	1		Front cover plate harness	Need Pattern
7809	P	P	1		Rear cover plate harness	Need Pattern
51009	P	P	1		Optional roof operation harness - for convertible only	

Sub harnesses are not illustrated. See Parts List.

